

90 Rankin Street, Unit 20/21 Waterloo, ON N2V 2B3 Tel: 519.747.7213 Fax: 519.747.7733 e-mail: office@billsnyderelectric.com www.billsnyderelectric.com

GOOD MANUFACTURING PRACTICES (GMPs)
FOR

FOOD SAFETY

- 1. Sign in at facility reception and review site-specific GMPs.
- 2. Remove all jewelry (watches, earrings, necklaces, chains, rings, etc.) prior to entering production areas. *Exceptions: Medic Alert necklace.*
- 3. Remove all loose items from upper pockets.
- 4. A plant supplied hair net must be worn to cover all exposed hair. The hairnet must be worn to cover the ears.
- 5. A beard net must be worn by those persons with facial hair below the upper lip or 1 day's growth.
- 6. Wear plant supplied overcoats or smocks if, and where, required.
- 7. Use of tobacco products, food or beverages, chewing gum, or medications is prohibited in production facilities. Use the designated welfare areas on site.
- 8. Wash Hands upon entering production areas, after visiting employee welfare areas, and prior to handling any food products or packaging materials.
- 9. Walk through foot baths or foot foam to minimize risk of contamination. Use SWARF mats where supplied, or brush off boots prior to entering production areas.
- 10. All cutting of materials is to be performed away from product zones, and shielding equipment is to be used as required.
- 11. Work areas are to be tidied up daily prior to leaving the facility and upon completion of the job.
- 12. Glass, razors, break-away utility blades, interchangeable screwdriver bits or needles are not permitted in the facility.
- 13. Sampling of product from production lines or storage warehouses is strictly prohibited.
- 14. Should a band-aid be required, obtain a metal detectable one from the site contact.
- 15. Do not prop doors open.
- 16. Report food safety concerns or contamination to the site contact immediately.

Issue Date: 08.25.10 Revision Date: new